Joint Service for Prevention and Protection at the port of Antwerp	Nr	C-VIK-026-E
SAFETY INSTRUCTION CARD	Date	24/01/2007
Storage of tankcontainers without lengthwise top or bottom beam	Page	1 of 1

1. RISKS

- Turnover of containers.
- Danger for crushing.
- Damaging tanks with possible exposure of people to dangerous products.

2. SAFE WORK INSTRUCTIONS

- 1. Mark storage place where tankcontainers need to be placed.
- 2. Sufficient distance between tankcontainers placed next to each other.
- 3. Tankcontainers may not be stacked, unlocked, on top of each other.
- 4. Obliged to place stackingcones or twistlocks at the 4 cornerpoints, when stacking the containers on top of each other.

3. PICTURES/DRAWINGS





4. PERSONAL PROTECTIVE EQUIPMENT







5. POINTS OF INTEREST



- Make sure work environment is safe when placing twistlocks or stackingcones.



Never stack tankcontainers, without lengthwise top or bottom beam, without locking.